



<u>FIG. 4</u>









FIG. 11






FIG. 13







FIG. 14













FIG. 18











The state of the s

11/15										
										λρ+99GHz
									7b-986Hz	λρ+88GHz
								7497644	λρ+87GHz	λp+77GHz
						/	7b-96GHz	λρ+86GHz	λp+76GHz	ур+66GHz
					/	Ap-95GHZ	λρ+85GHz	λρ+75GHz	лр+65GHz	λp+55GHz
				/	Ap+94GHZ	λρ+73GHz λρ+84GHz	λp+74GHz	λρ+64GHz	λρ+54GHz	λρ+33GHz λρ+44GHz
				λρ+93GHz	λρ+83GHz	λp+73GHz	λp+63GHz	λρ+53GHz	λp+43GHz	λρ+33GHz
			λρ+92GHz	λρ+82GHz	λp+72GHz	λp+62GHz	λρ+52GHz	λρ+42GHz	λp+32GHz	λp+22GHz
		λρ+91GHz	λρ+81GHz	λρ+71GHz	λp+61GHz	λρ+51GHz	λρ+41GHz	λp+31GHz	λp+21GHz	λp+11GHz
λρ≠160GHz	λρ+90GHz	λρ+80GHz	λρ+70GHz	λρ+60GHz	λρ+50GHz	λρ+40GHz	λp+30GHz	λp+20GHz	λp+10GHz	ур

1 Ghz STEP, TYPE 2 COMB

10 Ghz STEP, TYPE 1 COMB





The lift of the same of the sa




FIG. 25

